
# SEPTICITY ACTION PLAN WANLIP STW

ACTION PLAN TO REDUCED SEPTICITY ON SITE AT WANLIP SEWAGE TREATMENT WORKS, DUE TO THE LACK OF RAINFALL OVER THE PAST 2 TO 3 MONTHS WE HAVE NOTICED HIGHER LEVELS OF ODOUR REPORTED FROM THE SURROUNDING AREA AROUND WANLIP STW, AFTER CARRYING OUT A REACTIVE ODOUR REPORT ON SITE WE HAVE SETUP SOME OVERPUMPING FROM THE OUTFALL OF THE WORKS TO REDUCE THE SECTICITY AROUND SITE TO REDUCE THE ODOUR COMING FROM SITE PAIRED WITH WE HAVE INCREASED CHEMICAL DOSING TO REDUCE THE ODOUR COMING THROUGH THE INCOMING SEWER ON THE NETWORK. ST Classification: UNMARKED


## ROUTE OF OVER PUMPING WANLIP STW



- Location of pumps
- Over pumping discharge point
  - Direction of pumping

### PUMP SETUP AT THE OUTFALL, FLOWS BEING DRAWN FROM TO ASSIST WITH SEPTICITY AROUND SITE.








#### OUTFALL OF FINAL EFFLUENT PIPEWORK SETUP

#### LAYOUT OF PIPEWORK ONSITE.







#### DISCHARGE POINTS INTO WORKS AT WANLIP STW

